



No Touch Forehead Infrared Thermometer

The following is about advance Fealter® No Touch Forehead Infrared Thermometer related, I hope to help you better understand No Touch Forehead Infrared Thermometer.

As a professional high quality Fealter® No Touch Forehead Infrared Thermometer manufacture, you can rest assured to buy Fealter® No Touch Forehead Infrared Thermometer from our factory and we will offer you the best after-sale service and timely delivery. We have achieved remarkable success in this domain as a result of our focused approach, timely delivery, and ethical company philosophy. The No Touch Forehead Infrared Thermometer is designed for body and forehead measurement of infants and adults. The device is also commonly used to measure the temperature of a baby bottle or bathtub, or a room (using the surface temperature function).

Features of Feature No Touch Forehead Infrared Thermometer

Precision no touch measurement

Optional Body or Surface temperature

Temperature alarm value can be set

Can store the last 32 measurement data

Automatic data retention and shutdown

Automatic range selection and resolution display at 0.1 $^{\circ}$ C (0.1 $^{\circ}$ F)

LCD backlight display

Safety Information

No Touch Forehead Infrared Thermometer is only for the purposes described in this manual.

No Touch Forehead Infrared Thermometer can only be used in an environment of +10 $^{\circ}$ C to +40 $^{\circ}$ C.

Do not expose the thermometer to electric shock.

Do not use the device in an environment where the relative humidity is higher than 85%.

Do not use this equipment near strong electromagnetic fields, such aswireless phones or mobile phones.

Keep the device away from water and heat, including direct sunlight.

Do not drop or strike the device. Do not use it if it is damaged.

Covering your forehead with hair, sweat, hat or scarf may affect the accuracy of the measurement. (See Article 10).

Keep the measurement distance at 3 ~ 5cm (see Article 10).

The body thermometer should be left in the room for 15 to 20 minutes before use.

Pingyang Peace Personal Protective Equipment Co., Ltd.

Email:peaceppe@outlook.com



After the forehead is covered with sweat or other factors, it may affect the accuracy of the measurement. Please measure the temperature behind the earlobe (see Article 10). Clean the glass with a cotton swab moistened with 75% alcohol.

Advice

The protective glass over the lens is the most important and fragile part of the thermometer, please take great care of it.

Do not recharge non rechargeable batteries, do not throw in fire.

Do not expose the thermometer to sunlight or water. If the problem persists, please contact our customer service.



PARAMETER

ITEM NAME	NON-CONTACT FOREHEAD INFRARED THERMOMETER
Response time	Only 1sec
Measuring Distance	3-5cm
Accuracy	±0.3°C (0.54°F)
In Body Mode	32.0~42.9°C (90 ~ 109.22°F)
Surface Temp Mode	0~60°C (32 ~140°F)
No Operation Standby	20 sec
Power voltage	3V(1.5V*2AAA)
Weight	G.W164g/N.W108g(Without battery)
Product size	122 (L) * 41 (W) * 147 (D) MM
Humidity Rate	<85%







Pingyang Peace Personal Protective Equipment Co., Ltd.



