

TEST REPORT

Client Name	Shenzhen TPH Technology Co.,Ltd
Name of product	Electric Breast Pump
Manufacturer	Shenzhen TPH Technology Co.,Ltd
Model	----
Test sort	Commission Test



CCIC Southern Testing Co.,Ltd.

Address: Electronic Testing Building, No. 43 Shahe Road, Xili Jiedao, Nanshan District, Shenzhen, Guangdong, China

P.C.: 518055

TEL: 86-755-26627338

FAX: 86-755-26627238

Internet: [http:// www.ccic-set.com](http://www.ccic-set.com)

E-Mail: manager@ccic-set.com

The authenticity of the report is subject to the encrypted electronic version, which can be verified through the CNCA website (<http://yz.cnca.cn>).



Customer information	Client	Shenzhen TPH Technology Co.,Ltd
	Address	5th Floor, Building NO. 29 East side , Lianchuang 2nd technology park, Bulan Road, Nanwan Community , Longgang District, Shenzhen
Sample information	Name of sample	Electric Breast Pump
	Model	----
	Lot number	----
	Material	Transparent PP, Transparent silica gel
	Manufacturer	Shenzhen TPH Technology Co.,Ltd
	Address	5th Floor, Building NO. 29 East side , Lianchuang 2nd technology park, Bulan Road, Nanwan Community , Longgang District, Shenzhen
	Factory	Shenzhen TPH Technology Co.,Ltd
	Address	5th Floor, Building NO. 29 East side , Lianchuang 2nd technology park, Bulan Road, Nanwan Community , Longgang District, Shenzhen
Test information	Sample Received	Nov. 08, 2019
	Testing Period	Nov. 08, 2019~ Nov. 13, 2019
	Test sort	Commission Test
	Item Requested	Bisphenol A
	Standard/ Foundation	With reference to EPA 3550C:1996 and EPA8321B:2007, Analysis was performed by HPLC
	Conclusion	See test result page(s).
Note	This report is the English version of report No. SET2019-14865	

Tested By:

Checked By:

Approved By:

Date:

Nov. 13, 2019

Date:

Nov. 13, 2019

Date:

Nov. 13, 2019

CCIC Southern Testing Co.,Ltd.

Add: Electronic Testing Building, No. 43 Shahe Road, Xili Jiedao, Nanshan District, Shenzhen, Guangdong, China (pc: 518055)

http://www.ccic-set.com Tel: 0755-26627338 Fax: 0755-26627238

Tested components Description:

Specimen No.	Components Description	Color and Material	Item
1	Electric Breast Pump	Transparent PP	Bisphenol A
2		Transparent silica gel	

Sample Photo:



Test Results:


Item	Sample No.	Test result (mg/kg)		MDL (mg/kg)
		1	2	
☆Bisphenol A		N.D.	N.D.	1

Note:

-MDL = Method Detection Limit

-N.D. = Not Detected(<MDL)

Test Process:



***** END OF REPORT *****



STATEMENT

1. The test report is invalid without stamp of laboratory.
2. The test report is invalid without signature of person(s) testing and authorizing.
3. The test report is invalid if erased and corrected.
4. Test results of the report is valid to the test samples if sampling by client.
5. “☆” item to be outside the scope of authorized by CNAS.
6. “☆” item to be outside the scope of CMA, the test method、 data and results are available for reference.
7. The test report shall not be reproduced except in full, without written approval of the laboratory.
8. If there is any objection to report, the client should inform issuing laboratory within 15 days from the date of receiving test report.