











Monitoring ID	23-0193930	Audit Date	8 June 2023
Monitored Party	NINGBO LONGTENG OUTDOOR PRODUCTS CO., LTD		
Site amfori ID	156-047240-001		
Auditor	Aries He		

## Photo Form


		
entrance overview	facility name	workshop building
		
workshop building	Office and production building	Warehouse
		
fire alarm	hydrant	hydrant test



COC



Secondary container for chemical



MSDS



Switch box with warning sign



suggestion box



Washing facility



first aid kit



Toilet




attendance recorder



drinking water



Eye washing facility



Evacuation passage





Emergency light and exit sign



Evacuation plan



Employee wear PPE



PPE Warning sign




Fire extinguishers



Notification card of Occupational hazard factors



Injection section



Extrusion blow section



Assembling and packing section


## Photo Form (Non-compliance)



NC7.6- Employee did not wear earplug and mask



NC7.7- No secondary container for chemical



NC7.13-Area switch box without inner cover and not locked